



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

June 2, 2008

Supervisor SW

Mine Name: Walker Iron Mine Placer	Permit Number: S0210038
Operator Name: Frank Nichols	Inspection Date: 04/25/2008
Inspector(s): Tom Munson	Time: 10 am-11:30am
Other Participants: none	Mine Status: inactive

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

As a new inspector to this area, this inspection was mainly to find the site and assess the amount of disturbance.

Inspection Summary:

I Gps'ed the boundary of the disturbance as 4.42 acres. The site was a collection of stockpiled crushed materials of different sizes from boulders to fines. There was a small trackhoe onsite as well as an abandoned crusher, a barrel, some landfill material, and wooden pallets.

Photos were taken to document site conditions.

Conclusions and Recommendations:

It was noticed that there was a significant amount of debris on site that needs to be cleaned up.

Inspector's Signature

Tm:pb

cc: (OPERATOR)

ed-ginouves@blm.gov

O:\M021-Iron\S0210038-WalkerIron\inspections\insp-S190024-05092008.doc